



U. S. Chemical Safety and Hazard Investigation Board RECOMMENDATION STATUS CHANGE SUMMARY

Report:	Philadelphia Energy Solutions (PES) Refinery Fire and Explosions
Recommendation Number:	2019-04-I-PA-R3
Date Issued:	September 26, 2022
Recipient:	Environmental Protection Agency (EPA)
New Status:	Open - Awaiting Response or Evaluation/Approval of Response
Date of Status Change:	Not Applicable – Initial Status

Recommendation Text:

Per the requirements in EPA Rule Procedures for Prioritization of Chemicals for Risk Evaluation Under the Toxic Substances Control Act, initiate prioritization to evaluate whether hydrofluoric acid is a High-Priority Substance for risk evaluation. If it is determined to be a High-Priority Substance, conduct a risk evaluation of hydrofluoric acid to determine whether it presents an unreasonable risk of injury to health or the environment. If it is determined to present an unreasonable risk of injury to health or the environment, apply requirements to hydrofluoric acid to the extent necessary to eliminate or significantly mitigate the risk, for example by using a methodology such as the hierarchy of controls.

Board Status Change Decision:

A. Rationale for Recommendation

On the morning of June 21, 2019, a pipe elbow in the Philadelphia Energy Solutions (PES) hydrofluoric acid (HF) alkylation unit ruptured. A large vapor cloud—composed of about 95% propane, 2.5% HF, and other hydrocarbons—engulfed part of the unit. The vapor cloud ignited, causing a large fire. Three explosions then occurred in the unit. The third explosion was the largest and occurred when a pressure vessel violently ruptured and flew across the Schuylkill River. Two other pressure vessel fragments, one weighing about 23,000 pounds and the other 15,500 pounds, landed in the PES refinery.

PES estimated that 5,239 pounds of HF and 676,000 pounds of hydrocarbons were released during the incident. The HF alkylation unit was severely damaged resulting in an estimated property damage loss of \$750 million. Five workers and a firefighter experienced minor injuries during the incident and response. On June 26, 2019, PES announced that the refining complex would be shutting down.

The U.S. Chemical Safety and Hazard Investigation Board (CSB) investigated the incident and found several safety issues to include process safety management and other safety related standards. There were issues with PES's mechanical integrity program and their verification of safety of equipment when new safety information is discovered and published in Recognized and Generally Accepted Good Engineering Practices (RAGAGEP). Additionally, the CSB identified

gaps regarding standards or regulations that address remotely operated emergency isolation valves, safeguard reliability in HF alkylation units, as well as inherently safer design considerations specific to the use of HF. As a result of these findings, the CSB issued three recommendations to the EPA. This status change summary addresses **CSB Recommendation No. 2019-04-I-PA-R3**.